

Magnetic Circuits

Let's build some magnets

We have already considered an infinitely long bar magnet.



$$\nabla \cdot \vec{B} = 0$$

$$\nabla \times \vec{H} = 0$$

$$\vec{H}_i = \vec{H}_o = 0$$


$$B_i = \mu_0 H_i + \mu_0 M$$

$$B_i = \mu_0 M$$

For NdFeB, $M = 1.02 \times 10^6 \text{ A/m}$,

$$B_i = 1.28 \text{ T}$$

Let's bend the magnet into a circle so it's manageable



Now what's B_i ?

(2)

$$\nabla \times H = 0$$


$$\oint \vec{H} \cdot d\vec{l} = 0 \Rightarrow H_c = 0 \Rightarrow B_c = \mu_0 M = 1.28 T$$

magnetomotive force

$$mmf = \oint \vec{H} \cdot d\vec{l}$$

(not a force)

Problem Can't use the magnet, because we can't get inside it. Solution - Cut a hole



Still no free currents so

$$mmf = \oint \vec{H} \cdot d\vec{l} = 0$$

Still no monopoles so $\nabla \cdot \vec{B} = 0 \Rightarrow B_o = B_c \equiv B$

(3)

~~$$H_0 = B / \mu_0$$~~

$$H_0 = B_0 / \mu_0 = B / \mu_0$$

$$B_i = B = \mu_0 H_i + \mu_0 M$$

$$\oint \vec{H} \cdot d\vec{l} = (2\pi R - s) H_i + s H_0 = 0$$

What direction does H_i point?

$$\nabla \cdot \vec{H} = -\nabla \cdot M \quad \text{at interface}$$

$$H_0 - H_i = -(-M)$$

~~$$H_0 - H_i = M$$~~



$$H_0 < H_i$$

$$\Rightarrow H_i < 0$$

$$H_i = \frac{B - \mu_0 M}{\mu_0}$$


$$(2\pi R - s) \left(\frac{B - \mu_0 M}{\mu_0} \right) + s \frac{B}{\mu_0} = 0$$

$$2\pi R \left(\frac{B}{\mu_0} \right) = (2\pi R - s) M$$

$$B = \left(1 - \frac{s}{2\pi R}\right) \mu_0 M$$

⇒ The magnetic field is reduced by a factor of the ratio of the gap size to the total path length.

Ex Electromagnet, N turns, radius R , gap s
iron μ_r



$B_i = B_o$ as before

$$\text{mmf} = \oint \vec{H} \cdot d\vec{l} = \cancel{B} s = H_i (2\pi R - s) + s H_o = NI$$

$$H_o = \frac{B}{\mu_0} \quad H_i = \frac{B}{\mu_0 \mu_r}$$

$$\frac{B}{\mu_0 \mu_r} (2\pi R - s) + s \frac{B}{\mu_0} = NI$$

5

$$B \left(\frac{2\pi R}{\mu_r} - \frac{s}{\mu_r} + s \right) = NI$$

$$B (2\pi R - s + \mu_r s) = \mu_r NI \quad (\text{Field no gap})$$

$$B (2\pi R + s(\mu_r - 1)) = \mu_r NI$$

$$B \left(1 + \frac{s(\mu_r - 1)}{2\pi R} \right) = \frac{\mu_r NI}{2\pi R}$$

$$B = \frac{1}{1 + \frac{s(\mu_r - 1)}{2\pi R}} \cdot \frac{\mu_r NI}{2\pi R}$$

So the field is down by a factor of

$$\frac{1}{1 + \frac{s(\mu_r - 1)}{2\pi R}}$$

from the non-gap field

$$\text{of } B = \frac{\mu_r NI}{2\pi R}$$


If the gap is $\frac{1}{10} 2\pi R$, the reduction is

$$\frac{10}{\mu_r - 1} \text{ which is large.}$$

Ferromagnetism

Some materials have a gigantic magnetic response due to an energetic favorability to align spins over large areas of the material. The most common compound is iron, so the materials are called Ferromagnetic Materials.

I had everyone magnetize a nail




So we have two states of magnetization corresponding to one state of applied field. \Rightarrow The ferromagnet remembers its history.

E-mail Rochae!

(2)

Let's build a device to investigate this.



Put an iron core in solenoid.

Solve for the fields, $\vec{J}_f = 0$

$$\Rightarrow \nabla \times \vec{H}_f = 0$$

\Rightarrow Same result as if the material was not present.


$$\oint \vec{H} \cdot d\vec{l} = I_f = N'I \ell = H_i \ell$$

$$H_i = NI' \quad H_o = 0$$

$$B_i = \mu_0 \mu_r H_i = \mu_r B_{air}$$

where B_{air} is field that would be produced in a air-filled solenoid. $B_{air} = \mu_0 H_i$

Lets Plot Magnetization against the applied field ($B_{air} = \mu_0 H$)




We reach a point where most applied field does not generate more magnetization. At this point, all the dipoles are aligned.

If we then turn off the applied field, the magnetization decreases but not to zero. At this point the material is a permanent magnet with magnetization density M_p .


4

To erase this magnetization, we apply a reverse current. Eventually we can drive the magnetization through a cycle from saturation in one direction to saturation in the other direction.



Now, plot this in terms of the magnetic field

$$\vec{B} = \underbrace{\mu_0 \vec{H}}_{\text{tiny}} + \mu_0 \vec{M}$$



This curve is called the hysteresis loop. It is different for every magnetic material.

Note, a magnetic device operating on AC power will be driven through this loop at the frequency of the device.

The energy lost in each cycle $(\frac{1}{2} \vec{B} \cdot \vec{H})$ will be the area of the curve.

⇒ Heat destroys magnets - Each magnet has a temperature, the Curie temperature, where magnetization is lost